
## Installation Instructions

112 9028 REPLACEMENT KIT FOR OUTPUT SHAFT BEARING 001 6013 ON MODEL 10S, 12S AND 12RS SHREDDERS

- 1. Bolt bearing (1) to bearing support (3).
- 2. Slide the bearing and support onto the output shaft.
- 3. Position the new bearing support on top of the old one so the output shaft is in the center of the hole in the end plate.
- 4. Weld the new bearing support to the old one. Loosen the bearing mounting bolts and add shims (2) as necessary to level the output shaft. Tighten the bearing mounting bolts.

## 112 9028 Kit consists of:

```
1 of 091 6001 1 3/4" PB Bearing
1 of 111 3460 Bearing Support
2 of 125 2918 Shim (16 Ga.)
3 of 001 2600 Shim (11 Ga.)
2 of 000 8140 1/2 - 13 X 2" HHCS (Grd. 5)
4 of 001 8257 1/2" SAE Flatwasher
2 of 000 8180 1/2" Lockwasher
2 of 000 8163 1/2 - 13 Locknut
```



MATHEWS COMPANY
P.O. Box 70, Crystal Lake, IL 60014